

**PATENT**

**IN THE UNITED STATES PATENT AND TRADEMARK OFFICE**

**Inventor(s):** Lee et al.

**Patent No.:** 7,057,297 B2

**Issued:** June 6, 2006

**For:** TAPE SUBSTRATES WITH MOLD  
GATE SUPPORT STRUCTURES THAT  
ARE COPLANAR WITH CONDUCTIVE  
TRACES THEREOF AND ASSOCIATED  
METHODS

**Attorney Docket No.:** 2269-5772US

**VIA ELECTRONIC FILING**

**August 21, 2007**

**REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT  
OFFICE MISTAKES (37 C.F.R. § 1.322)**

Attn.: Certificate of Corrections Branch  
Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

Sir:


It is noted that several errors appear in this patent of a typographical nature. These errors are due to mistakes in printing on the part of the U.S. Patent and Trademark Office, and occurred through no fault of the Applicants. A certificate of correction in the form attached hereto is requested.

Please send the Certificate to:

Name: Brick G. Power  
Address: TraskBritt  
P.O. Box 2550  
Salt Lake City, Utah 84110

Attached hereto in duplicate is Form PTO/SB/44 with at least one copy being suitable for printing.

Respectfully submitted,

A handwritten signature in black ink, appearing to read "Brick G. Power", written over a horizontal line.

Brick G. Power  
Registration No. 38,581  
Attorney for Applicant(s)  
TRASKBRITT, PC  
P.O. Box 2550  
Salt Lake City, Utah 84110-2550  
Telephone: 801-532-1922

Date: August 21, 2007  
BGP/df:ec

Enclosures: PTO/SB/44 in duplicate

Document in ProLaw

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO : 7,057,297 B2  
DATED : June 6, 2006  
INVENTOR(S) : Teck Kheng Lee; and M. Vijendran

Page 1 of 1

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

**In the claims:**

CLAIM 12, COLUMN 8, LINE 56,  
CLAIM 12, COLUMN 8, LINE 58,

change "them old gate" to --the mold gate--  
change "dielectric films, the support element  
at least partially" to --dielectric film, the  
support structure at least partially--

MAILING ADDRESS OF SENDER:

PATENT NO. 7,057,297 B2

Brick G. Power  
230 South 500 East, Suite 300  
Salt Lake City, Utah 84102 USA

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS.  
**SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.**

*If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.*